

Operating Instructions
Bedienungsanleitung
Mode d'emploi
Gebruiksaanwijzing
Istruzioni per l'uso
Instrucciones para el
manejo



WEBTEC

HPM110

Contents

1	Introduction	2
	1.1 Notes on safety / production selection	2
	1.2 Device versions and range of delivery	3
2	Commissioning	4
	2.1 Replacing the batteries	4
3	Functions and keys	6
	3.1 Display mode	8
	3.2 Menu functions	9
4	Connection to the hydraulics	11
5	Operating the HPM110	13
	5.1 Turning on (ON)	13
	5.2 Turn off (OFF)	14
	5.3 Turn on backlight	14
	5.4 MIN/MAX indication	14
	5.5 FS Full Scale display	15
	5.6 Erasing the MIN/MAX values	15
	5.7 OFL Display	15
	5.8 Zero point correction (ZERO)	15
	5.9 Resetting the zero point correction	17
	5.10 Automatic power off	17
	5.11 Changing the unit	18
	5.12 Filter settings	19
	5.13 Display serial number	20
6	Technical data	21

1 Introduction

The HPM110 is a digital manometer featuring a Min/Max display function. Full scale (FS) accuracy is $\pm 0.5\%$ based on the upper limit of the measurement range.

Dynamic pressure peaks are measured at a scanning rate of 10ms (100 measurement values/second). The MIN/Max memory is continuously updated and rewritten.

1.1 Notes on safety / product selection

The correct functioning of the HPM110 can only be guaranteed when the specifications detailed in these operation instructions are adhered to. In particular, specifications relating to the permitted upper limit of the measurement range as well as the permissible temperature range must be observed.



Serious malfunctions leading to personal injury or damage to property can result from using the chosen product in applications that do not comply with the specifications or from disregarding the operating instructions. In particular, incorrect mounting of the manometer and the corresponding adapter can cause the manometer to be torn out of the assembly.

For repairs or calibration of the measurement instruments, please contact a Webtec sales branch.

1.2 Device versions and range of delivery

Device versions / range of delivery			
Basic setting to unit 'bar' Pressure connection, male thread G1/4		Basic setting to unit 'PSI' Pressure connection, male thread UNF 7/16-20	
Delivery with adapter M16x2		Delivery without adapter	
Measurement range	Order No.	Measurement range	Order No.
0...100.0	SR-HPM-110-MT-100	0...1500	SR-HPM-110-UN-1500
0...600.0	SR-HPM-110-MT-600	0...8700	SR-HPM-110-UN-8700



2 Commissioning

The HPM110 is supplied with batteries fitted.
The device is operational as soon as it is turned on.


2.1 Replacing the batteries




Caution!

Turn off the device before replacing the batteries. Open the battery compartment. Insert the new batteries as depicted. Ensure correct polarity of the batteries.

Batteries: 2 x 1.5 V (LR6 - AA)





When in continuous operation (without light), the service life of the batteries is 1,500 hours.



A battery symbol permanently displays the actual battery status.

3 Functions and keys








Display

- 4½ digit LCD with backlight
- Displays measurement values and menu functions

- ① Bar graph with Peak & Hold function
- ② Actual value display (15mm)
- ③ MIN/MAX or Full Scale
- ④ (8mm) Battery status

Keys




Key	Function	
	ON/OFF 	Turns the device on / off. Press for 2 seconds. Turns on the backlight (stays on for 20 seconds).
	MIN MAX FS	Selects display unit: MIN, MAX or FS Minimum value Pressure peak Displays the upper limit of the scale (e.g. 600 bar)
	MENU ZERO	Press for 2 seconds. Changes the unit. Auto Power Off – on/off. Zero point calibration.
	RESET OK	Erases MIN and MAX values from the memory. Confirms the MENU functions.

3.1 Display mode

The actual pressure (ACT) is indicated in the display mode. The ACT measured value is displayed in the corresponding unit. The MIN, MAX or FS values is indicated in the lower part of the display.

Display	Description
Bar graph	Graphic indication of the actual pressure. A pressure peak is indicated by means of a pixel (graduation mark). The indicated value is refreshed at intervals of 50 ms (20 measurements/s).
ACT	Indicates the actual pressure. The indicated value is refreshed at intervals of 300 ms (3 times/s).
MIN/MAX	Indicates the MIN, MAX or FS value according to setting. The indicated value is refreshed at intervals of 300 ms (3 times/s).
FS	Upper limit of the scale (e.g. 600 bar).
Units	Indicates the chosen unit.

	Indicates the battery status (5 segments).
x10	Indicated value (actual indication and MIN/MAX indication) x10.7

3.2 Menu functions

The following settings can be made in the MENU function:

- Auto Power Off – on or off
- Unit selection (bar, mbar, PSI, kPa, Mpa)

Press the MENU key for 2 seconds to activate the functions menu.

Press the MENU key again to select the next function.

Press the OK key to save the function setting.

The device then switches to the display mode.

4 Connection to the hydraulics

The HPM110 is available with male thread G1/4 (BSPP) or 7/16-20 UNF for the corresponding versions (bar/PSI).



Observe specified torques when fitting the HPM110

The spanner size of the pressure connection is 27 mm

Pressure connection	Torque
7/16-20 UNF	35 Nm
1/4 BSPP	25 Nm

When fitting directly, please ensure the HPM110 can be rotated freely.



5 Operating the HPM110

5.1 Turning on (ON)



A self-test procedure is carried out



The measuring range is indicated (FS)

Unit (bar) SR-HPM-110-MT-XXX

Unit (PSI) SR-HPM-110-UN-XXXX



Auto Power Off function is active. Power off activates automatically after 5 minutes. This function can be altered in MENU.



Display mode:
ACT value displayed

5.2 Turn off (OFF)

Press once (briefly)  .

5.3 Turn on backlight

Press  for 2 seconds.

The backlight goes out automatically after 20 seconds.

5.4 MIN/MAX indication

Use this key to toggle the required value.

The key function is sequential; the values are indicated in the display in sequence.

The MIN/MAX function is used to measure pressure peaks. The respective lowest (MIN) and highest (MAX) measured values are stored in the MIN/MAX memory. Values in the MIN/MAX memory are erased when the device is turned off. If different pressure tests are to be carried out in succession, the MIN/MAX memory must be erased after each measurement.



MIN/MAX/FS value is indicated in the display.

5.5 FS Full Scale display

Displaying the upper limit of the scale (FS) is designed to increase readability of the bar graph function.

The upper limit of the measurement range is indicated numerically.

FS is indicated in sequence after MIN and MAX.



FS is displayed.

5.6 Erasing the MIN/MAX values



Erases MIN/MAX values.

5.7 OFL Display



This indicates that the applied pressure is outside given full scale range.

If the message remains displayed when the HPM110 is disconnected from the pressure source, please consult a Webtec Sales Office.

5.8 Zero point correction (ZERO)

The zero point can be corrected manually should undesired deviations occur when no system pressure is being applied (atmospheric pressure).



Caution!

The zero point correction sets the current ACT value to zero. In order to exclude erroneous measurements, ensure no system pressure is being applied when carrying out this function.



This initiates the zero point correction. The ACT (actual) value is indicated in the display as 0.0 bar. The correction remains active until the device is turned off.



OFL/ZERO is displayed for 3 seconds if the measured pressure (0 bar) is greater than 5% of the measurement range.

Zero point correction cannot be carried out. Please ensure that no system pressure is being applied.

5.9 Resetting the zero point correction



Turn off the device. Zero point correction is no longer active when the device is turned off and on again.

5.10 Automatic power off

Press  for 2 seconds.

Depending on the device configuration, two different displays are possible:

Auto Power Off




PO On

Press . Auto Power Off is activated after 5 minutes.

Continuous operations



PO OFF

Press . The device must be turned off manually.



The settings Auto Power Off or Continuous operations remain stored and are active when the device is turned off and on again.

5.11 Changing the unit


Press  for 2 seconds.




Press  .



Press once (briefly)  .





The next unit is indicated



Confirm unit selection.

(Measurement range
16 bar/230 PSI)



5.12 Filter settings


Press  for 2 seconds.



Press  .



Press  .



Press once (briefly)  .

Filter selection is indicated.

 Confirm filter configuration.

5.13 Display serial number

Press  .



Display of serial number (1. line).
Display of software version (2. line).



6 Technical data

Version	<ul style="list-style-type: none"> - Digital pressure gauge with ACT - MIN and MAX Display - bar graph display 33 segments (with peak and hold function) - 4 1/2 digit LC display (15 mm) with back light illumination - Battery powered with low power electronic system - Life time cycle 1,500 h (No back light function) <p>Pressure port stainless steel 1.4404</p>
Input	<ul style="list-style-type: none"> - 1/4 " BSPP (ISO 1179-2) or 7/16-20 UNF (ISO 11926-2/3) - Strain Gauge Cell 0...100/600 bar - Scan rate 10 ms - Resolution 12 bit = 4,096 steps
	<ul style="list-style-type: none"> - Accuracy ± 0.25 % FS typ. ± 0.5 % FS max.
Housing	<p>$\varnothing = 79$ mm; T = 33 mm</p> <p>Zinc Die Cast with Rubber Protection TPE</p>
Sealing	<p>Standard NBR sealed Viton® (FKM); EPDM on request</p>

Parts in contact with media	Stainless Steel 1.4404, NBR
Power supply	Battery 2 x1,5 VDC (LR6 –AA) Alkaline (Mignon)
Ambient conditions	Operating temperature: -10...50 °C Fluid temperature : -20...80 °C Storage temperature: -20...60 °C Rel. humidity: < 85 % Protection: EN 60529 (IP 67) Vibration: IEC 60068-2-6 5 g Shock: IEC 60068-2-27 25 g Reliability Cycles (10⁶): 100

Digital Manometer HPM110

Range bar	Display bar	Display PSI	Display mbar
0...100	0...100.0	0...1500	-
0...600	0...600.0	0...8700	-

ENGLISH

Range bar	Display kPa	Display MPa
0...100	0...10000	0...10.00
0...600	0...6000 (x10)	0...60.00

Meas. range (bar)	0...100	0...600
Overload P_{max} (bar)	200	1200
Burst pressure (bar)	800	2200



Exceeding the maximum overload values (Pmax) can lead to malfunctions and result in the HPM110 being destroyed.

Burst pressures are based on data without the M16x2 adapter.

The HPM110 meets the guidelines of the European Community (EU). It is confirmed that this product is approved acc. to following standards:



DIN / EN 61000-6-2

DIN / EN 61000-6-3

Technical data subject to change.

February 2006

